



भारतीय अन्तर्देशीय जलमार्ग प्राधिकरण
(पोत परिवहन मंत्रालय, भारत सरकार)
INLAND WATERWAYS AUTHORITY OF INDIA
(MINISTRY OF SHIPPING, GOVT. OF INDIA)

Regional Office : Pandu Port Complex, Pandu, Guwahati – 781 012 (ASSAM)

• Telefax No. 0361-2570099, 2570055 • Ph. No. 0361-2570109, 2676925, 2676927, 2676929

• E-mail : iwaighy@yahoo.co.in / dirguw.iwai@nic.in • Gram : JALMARG

No. IWAI/GHY/Ro-Ro/4(105)/2019-20/104

Date: 02.07.2021

To,

M/s A.C. Roy & Co.
Room no. 1505,
Diamond Heritage Building,
16, Stand Road, Kolkata – 700 001

Sub: Award of work for “Dry Dock – Afloat Repair of Ro-Ro vessel M.V. Gopinath Bordoloi at Kolkata / Howrah” – reg.

Ref: 1) NIT No.: IWAI/GHY/Ro-Ro/4(105)/2019-20
2) Bid no.: ACD/012/2021-2022, dated 23.04.2021

Sir,

Inland Waterways Authority of India (IWAI) is please to award the work for “**Dry Dock – Afloat Repair of Ro-Ro vessel M.V. Gopinath Bordoloi at Kolkata / Howrah**” at a total cost of **Rs.25,41,480/-** (Twenty Five Lakh Forty One Thousand Four Hundred and Eighty only) plus GST as applicable in accordance with the terms & conditions of the contract. Details Bill of quantity is attached as Annex – I.

2. You are requested to deposit an amount of **Rs.1,27,074/-** (One Lakh Twenty Seven Thousand and Seventy Four only) i.e., 5% of the contract value of the work either in the form of RTGS / Demand Draft issued by scheduled / nationalized banks in favour of “IWAI FUND PLAN” payable at Guwahati or in the form of irrevocable bank guarantee of any scheduled bank towards Performance Guarantee within 15 days from the issue of this letter as per **Clause 3** of General Conditions of Contract (GCC). In addition to the above, a security deposit equivalent to 5% of the contract value (i.e **Rs.1,27,074/-**) will be deducted from your RA bills as per **Clause 4** of the General Conditions of Contract.

3. The payment shall be made as per the Bill of Quantity on satisfactory completion & certification of the items of works by EIC or his authorize representative. While submitting the bills, you have to indicate GST also, which may be paid by this office as per norms.

4. Time is an essence of this work. The whole work has to be completed within a period of **45 days** from the date of handing over the vessel. The work has to be completed as per Tender terms & conditions.

Cont.....P/2



भारतीय अन्तर्देशीय जलमार्ग प्राधिकरण
(पोत परिवहन मंत्रालय, भारत सरकार)
INLAND WATERWAYS AUTHORITY OF INDIA
(MINISTRY OF SHIPPING, GOVT. OF INDIA)

Regional Office : Pandu Port Complex, Pandu, Guwahati – 781 012 (ASSAM)


• Telefax No. 0361-2570099, 2570055 • Ph. No. 0361-2570109, 2676925, 2676927, 2676929

• E-mail : iwaighy@yahoo.co.in / dirguw.iwai@nic.in • Gram : JALMARG

-2-

5. Director, IWAI, Guwahati shall be the Engineer-In-Charge for the subject work.
6. You are requested to acknowledge the receipt of this work order and attend this office along with two non-judicial stamp paper of Rs. 100/- to enter into an agreement.

Encl. As stated above.

Yours faithfully,

(SURENDRA SINGH)
DIRECTOR

Copy to:

1. The Member (Technical), IWAI, Noida.
2. The Member (Traffic), IWAI, Noida.
3. The Chief Engineer (Tech.), IWAI, Noida.
4. The Director (Marine), IWAI, Noida – For information please.
5. The Director, IWAI, Kolkata.
6. The Accounts Officer, IWAI, Guwahati.

Validate

Print

Help

Item Rate BoQ

Tender Inviting Authority: Inland Waterways Authority of India

Name of Work: Dry Dock -Afloat repair of RoRo Vessel M.V. Gopinath Bordoloi at Kolkata/ Howrah

Contract No: IWA/GHY/Ro-Ro/4(105)/2019-20

Length- 46.50 M, Breadth- 13.30 M, Depth- 3.0 M, GRT- 388

Bidder Name : A. C. ROY & CO.

PRICE SCHEDULE

(This BOQ template must not be modified/replaced by the bidder and the same should be uploaded after filling the relevant columns, else the bidder is liable to be rejected for this tender. Bidders are allowed to enter the Bidder Name and Values only)

NUMBER	TEXT #	NUMBER #	TEXT #	NUMBER #	NUMBER #	TEXT #
Sl. No.	Item Description	Quantity	Units	BASIC RATE In Figures To be entered by the Bidder Rs. P	TOTAL AMOUNT Without Taxes	TOTAL AMOUNT In Words
1	2	3	4	5	6	7
1.00	Docking & undocking Dock hire charge and mooring charges as required is to be done for completion of repair works for 60 days.	1	Comp. Job	160000.00	160000.00	INR One Lakh Sixty Thousand Only
2.00	Ultrasonic testing is to be done of hull , side plate & deck plate for measurement of thickness as per direction of IWT surveyor/EIC.	200	Spot	60.00	12000.00	INR Twelve Thousand Only
3.00	Cropping & renewal of underwater plate, deck plate , Ship side plate & other fitments as required as per direction of IWT surveyor EIC.	100	Kg	100.00	10000.00	INR Ten Thousand Only
4.00	All sea chest, mud box, strainer is to be checked, repaired ,cleaned and painted as per direction of EIC/IWT Surveyor.	1	Comp. Job	30000.00	30000.00	INR Thirty Thousand Only
5.00	All main sea suction valve and Line valve along with its entire pipe line is to be checked, tested and serviced, repaired/ renewed including other fitting of valve in entire ship as per direction of IWT surveyor/ EIC.	1	No	110000.00	110000.00	INR One Lakh Ten Thousand Only
6.00	Under water hull plate and side plate is to be scrapped wire brush and chipped from Keel to LWL as required as per direction of EIC/IWT Surveyor.	798	Sq.m	60.00	47*80.00	INR Forty Seven Thousand Eight Hundred & Eighty Only
7.00	Painting of the underwater hull plate & side plate is to be done by 3 coat as per Painting scheme from keel to water level as per direction of IWT Surveyor/ EIC.	798	Sq.m	180.00	143640.00	INR One Lakh Forty Three Thousand Six Hundred & Forty Only
8.00	The entire ship side shell plate from LWL to main deck is to be scrapped, wire brushed, chipped & cleaned.	179	Sq.m	60.00	10740.00	INR Ten Thousand Seven Hundred & Forty Only
9.00	The entire ship side shell plate from LWL to main deck are to be painted by three coat as per painting scheme of marine quality paint as per direction of IWT Surveyor/ EIC.	179	Sq.m	180.00	32220.00	INR Thirty Two Thousand Two Hundred & Twenty Only
10.00	Main deck, super structure, wheel house, engine room, both ram, kitchen, toilet, bollard, hatch etc. are to be properly cleaned chipped, scrapped, wire brushed and painted by two coats of marine paint as per direction of Surveyor/EIC.	1500	Sq.m	150.00	225000.00	INR Two Lakh Twenty Five Thousand Only
11.00	All water tank is to be cleaned properly & painted/cemented as per direction of Surveyor/EIC.	1	Comp. Job	25000.00	25000.00	INR Twenty Five Thousand Only
12.00	All HSD tank (Reaserve tank of KL - 2 nos & Service tank - 5 nos),is to be cleaned properly as per direction of IWT surveyor/EIC.	1	Comp. Job	30000.00	30000.00	INR Thirty Thousand Only
13.00	Port & Stbd side propeller, propeller shafts and it bushes are to be opened for finding out clearance & checking of truness, bulidup of bushes, shaft, A Bracket and blade etc repaired and fitting back in OE position as per drawing after fairing with same composition of materials/renewed the bushes, balancing, bedding etc as required asper direction of Surveyor	2	Comp. Job	180000.00	360000.00	INR Three Lakh Sixty Thousand Only
14.00	Both rudder assembly to be dismantled, rudder stock,shaft,bushes to be checked and if required same to be bulidup asper OE Size and fitted back in position asper direction of IWT Surevor	2	Comp. Job	75000.00	150000.00	INR One Lakh Fifty Thousand Only

15.00	Rudder indicator is not working same to be rectify & repaired including labour and material	1	Comp. Job	25000.00	25000.00	INR Twenty Five Thousand Only
16.00	Toilet flausher, plumbing work and passenger urinal commode Syntex tank valve found cracked and cover damaged including labour & materials	2	No	15000.00	30000.00	INR Thirty Thousand Only
17.00	Wheel house door (01) and crew cabin doors and door lock of toilet to be repaired including labour & materials	1	Comp. Job	15000.00	15000.00	INR Fifteen Thousand Only
18.00	Anchor guard are broken frequently. Anchor guard to made properly including labour and materials as per direction of IWT surveyor.	1	Comp. Job	20000.00	20000.00	INR Twenty Thousand Only
19.00	All electrical Line panel AC/DC ,Navigation, light of wheel house, engine room (including emergency lights), deck and its line & wiring is to be checked and serviced/ repaired as required with renewal of required materials as per direction of EIC/IWT Surveyor.	1	Comp. Job	150000.00	150000.00	INR One Lakh Fifty Thousand Only
20.00	Fire extinguisher to be serviced, refilling and tested (hydraulic) & certificate is to be produced as per direction of EIC/IWT Surveyor.					
20.01	Mechanical Foam type – 9 ltrs.	4	No	2000.00	8000.00	INR Eight Thousand Only
20.02	DCP – 5 Kg	6	No	2000.00	12000.00	INR Twelve Thousand Only
21.00	Fire hydrant valve is to be serviced including material	1	Comp. Job	5000.00	5000.00	INR Five Thousand Only
22.00	All bilges, sewage are to be cleaned including labour and all materials.	1	Comp. Job	75000.00	75000.00	INR Seventy Five Thousand Only
23.00	STBD - M/E opened due to sea water dilution in cylinder head through exhaust line. Sam engine to be refilled with renewal of minimum spare parts as per recommendation of IRS Surveyor	1	Comp. Job	750000.00	750000.00	INR Seven Lakh Fifty Thousand Only
24.00	Aft windless transmission box generating sound and shaft found jerking, same to be rectify including labour and material	1	Comp. Job	40000.00	40000.00	INR Forty Thousand Only
25.00	Aft ramp safety wire broken, same to be replaced	1	Comp. Job	25000.00	25000.00	INR Twenty Five Thousand Only
26.00	Passenger seating space panel damaged, same to be repair	1	Comp. Job	20000.00	20000.00	INR Twenty Thousand Only
27.00	All hatch cover and ventilator rubber packing to be renewed	1	Comp. Job	20000.00	20000.00	INR Twenty Thousand Only
Total in Figures					2541480.00	INR Twenty Five Lakh Forty One Thousand Four Hundred & Eighty Only
Quoted Rate in Words		INR Twenty Five Lakh Forty One Thousand Four Hundred & Eighty Only				