

Comparative statement on financial Bid for Annual afloat repair of MV Homi Bhabha for the year 2023-24
Tender ID: 2023_IWAI_770464_2


Tender No. IWA/IKO-150MN38/1/2021


Date of opening of price Bid:

Sl.No	Description of Work / Item(s)	Qty	Units	IWAI Estimated cost		M/s FRENCH ENTERPRISE		M/s Maa Vindhya wasni Enterprises	
				Rate	Amount	Rate	Amount	Rate	Amount
1.00	Port side main engine exhaust trucking pipes to be repaired with lagging with glass wool & ducting with aluminium sheet, and water proofing of exhaust pipes from deck side & changing of damaged Nuts and bolts as per direction of EIC/Surveyor.								
1.01	Labour charges	1	Comp. Job	20500	20500.00	20500	20500.00	20500	20500.00
1.02	Cost of spares (actual + 10%)								
2.00	Entire electrical/ electronic system including both AC, DC panels and emergency of wheel house, engine room, cargo hold, deck, accommodation, kitchen, toilet, blowers, vents, navigation lights with panels, CVS, Echo sounder, fans, lights, safety systems, pressure gauges, meters, main engine panel board, generator engine panel board, etc and its line to be checked and serviced/ repaired as required in wheel house, engine room, accommodation & other stations, with renewal of required materials as per direction of EIC/ Surveyor.								
2.01	Labour charges	1	Comp. Job	50000	50000.00	50000	50000.00	50000	50000.00
2.02	Cost of spares (actual + 10%)								
3.00	Bilge, fire, GS, ballast etc pumps to be serviced along with installation of proper protective cover of rotational parts such as couplings as required as per direction of EIC/ IWT Surveyor.								
3.01	Labour charges	4	Comp. Job	4000	16000.00	4000	16000.00	4000	16000.00
3.02	Cost of spares (actual + 10%)								
4.00	Port side anchor shank found bend condition and same to be make straight as per OEM position including labour charge as required as per direction of EIC/ IWT Surveyor	1	Comp. Job	10000	10000.00	10000	10000.00	10000	10000.00
5.00	Propeller shaft and Main engine RPM meter of Both side in wheel house reported out of order the same has to be renewed/ repaired with reputed make and also main engine & genset engine radiator tank cover have to supply as required as per direction of Surveyor/EIC.								
5.01	Labour charges	4	Comp. Job	10000	40000.00	10000	40000.00	10000	40000.00
5.02	Cost of spares (actual + 10%)								
7.00	All manhole and hatches cover of rooms, vents and wheel house etc's gasket and packing has to be replaced. Nut bolts has to be replaced with Stainless Steel as required as per direction of EIC/ IWT Surveyor.								
7.01	Labour charges	1	Comp. Job	15000	15000.00	15000	15000.00	15000	15000.00
7.02	Cost of spares (on Actual + 10 % basis)								
8.00	Anchor windlash along with motor, gear,oil glass gauge, brake shoe, anchor chains, its all accessories to be inspected and repaired/ serviced with renewal of spare-parts as required as per direction of EIC / IWT Surveyor.								
8.01	Labour charges	1	Comp. Job	11000	11000.00	11000	11000.00	11000	11000.00
8.02	Cost of spares (on Actual + 10 % basis)								
Total Amount (in Rupees)					162500.00		162500.00		162500.00
Quoted rate in percentage (excess(+)/ less(-))					0.00		(-) 11.00		(+) 6.00
Total Quoted Amount					1,62,500.00		1,44,625.00		1,72,250.00
Percentage variation					%		-11.00		6.00
								L-1	L-2

R.O. Kolkata TEC, scrutinised the bids of three(2) technically qualified bidder and observed that M/s FRENCH ENTERPRISE, Kolkata is L-1 bidder has quoted Rs. 1,44,625.00 plus GST and cost of spare on actual plus 10% basis which is lowest (-11.00%) then estimated cost Rs.1,62,500.00/-

TEC recommends that work may be awarded to L-1 bidder i.e. M/s FRENCH ENTERPRISE, Kolkata at the quoted price of Rs.1,44,625.00 (excluding GST) plus cost of spare on actual +10% basis with approval of the approval of Competant Authority.


(Mukul Jain)
Asstt. Director


(Ajay Kar)
Sr. A.O


(Arvind Kumar)
Director