



भारतीय राष्ट्रीय राजमार्ग प्राधिकरण

(सड़क परिवहन और राजमार्ग मंत्रालय, भारत सरकार)

NATIONAL HIGHWAYS AUTHORITY OF INDIA
(Ministry of Road Transport & Highways, Government of India)

क्षेत्रीय कार्यालय - हैदराबाद

डो. नं. ८-२-२६९/एस/९४, तीसरी और चौथी मंजिल, प्लॉट नंबर 94, रोड नं.2, सागर सोसाइटी, बंजारा हिल्स, हैदराबाद-500034, तेलंगाना.

REGIONAL OFFICE - HYDERABAD

D.No. 8-2-269/S/94, 3rd & 4th Floors, Plot No.94, Road No.2, Sagar Society, Banjara Hills, Hyderabad-500034, Telangana.

टेली / Tele : 040 - 29562147 / 48 ई-मेल / Email: rohyderabad@nhai.org / nhairohyd@gmail.com
NHAI/RO-HYD/NH-563/WGL-KMM/O&M/Pkg-1/2025/1384

Dt.22 .08.2025

To
All the Prospective Bidders

Sub: NHAI - RO Hyderabad - PIU Khammam-I - Short Term Improvements and Routine Maintenance of 2/4-lane with paved shoulder stretch from Km 132+650 to Km 194+000 on Warangal to Khammam section of NH-563 in the state of Telangana - **Technical Evaluation Results - Reg.**

Ref: 1. NIT no. NHAI/RO-HYD/NH-563/WGL-KMM/O&M/Pkg-1/2025/22 dt:24.07.2025
2. Tender ID: 2025_NHAI_242495_1

<><><>

Dear Sir/ Madam,

With reference to the above NIT and consequent upon finalization of technical evaluation, the responsiveness of the bidders is as below:

S. No.	Name of the Bidder	Responsiveness
1	M/s. Perfect Allied Safety and Security Services Pvt. Ltd	Technically Non-Responsive - Didn't furnish Experience Certificates & Proof of Age of proposed Key Personnel as per Cl.4.4.B (b) (ii) of Section-II, ITB of RFP. - The bidder has furnished a Lease Agreement for Air Compressor, however, the proof submitted pertains to a Tractor instead of the Air Compressor. - The bidder has furnished a Lease Agreement for Mobile Road repair & Patching Machine. However, the furnished proof of equipment pertains to Slurry Paver, whereas as per the provisions of the RFP, a Mobile Road Repair & Patching Machine is required.
2	M/s. Sri Venkateshwara Constructions	Technically Non-Responsive. - Didn't furnish Experience Certificates of proposed Key Personnel as per Cl.4.4.B (b) (ii) of Section-II, ITB of RFP. - The bidder has furnished availability certificate of machinery/equipment with the contractor, certified by the Executive Engineer. However, proof of ownership of any equipment is not furnished. - The bidder has furnished a lease agreement for Road Marking Machine. However, the age of equipment is more than 5 years.

2. Therefore, as per provisions of clause 31.1, ITB of RFP, the Authority has annulled the bidding process and fresh bids will be invited shortly.

This issues with the approval of CGM(T) & Regional Officer.

Yours faithfully

(G V Bheemasena Reddy)
Dy. General Manager (Tech)
Regional Office, Hyderabad.