

GOVERNMENT OF ARUNACHAL PRADESH
PUBLIC WORKS DEPARTMENT

Email: - cehwzone@gmail.com
Ph. No. 0360-2290543

OFFICE OF THE CHIEF ENGINEER
HIGHWAY ZONE PWD :: AP :: ITANAGAR

No. CEAP(HW)/WTC-161/OR/PP/2023-24/

Dated : 01.03.2024

OFFICE MEMORANDUM

The Bid Evaluation Committee meeting held on 26.02.2024 for evaluation of technical bids for the work "Repair and Maintenance works on Jonai-Pasighat Road section of NH-515 from Km 510.00 to Km 522.00, Km 522 to Km 536.00 & Km 536.00 to Km 550.150 under STMC in the state of Arunachal Pradesh (Job No. RW/ITA/STMC/Ar.Pr./23-24/8) has found the technical bids of the following bidders responsive and qualified.

Therefore, it is notified to all concerned that the Financial Bids of the responsive and qualified bidders shall be opened on 04.03.2024 at 3.00 PM in the office of the Chief Engineer, Highway Zone, Itanagar. Interested qualified bidders may attend the financial bid opening.

Sl. No	Name of Bidders
1	M/s N M Enterprises
2	M/S Puna Hinda


Sd/-
Chief Engineer
Highway Zone,
PWD AP, Itanagar

No. CEAP(HW)/WTC-161/OR/PP/2023-24/ 5183-89

Dated : 01.03.2024

Copy to:-

1. The Regional Officer, MORTH, Itanagar (Tezpur) for information.
2. The Superintending Engineer, Highway Zone for information.
3. The Sr. Finance & Accounts Officer, Highway Zone for information.
4. The Executive Engineer, Pasighat Highway Division, Pasighat for information.
5. M/s N M Enterprises for information.
6. M/S Puna Hinda for information
7. Miss Aruna Deru, DBA MoRT&H, Itanagar. She is directed to upload immediately.


Chief Engineer,
Highway Zone, PWD, AP,
Itanagar

BY ROTATION

Minutes of Meeting of Technical Bid Evaluation held on 26.02.2024 under the
Chairmanship of Executive Engineer, Pasighat Highway Division, PWD, Pasighat

Name of Work	Repair and Maintenance works on Jonai-Pasighat Road section of NH-515 from Km 510.00 to Km 522.00, Km 522.00 to Km 536.00 & Km 536.00 to Km 550.150 under STMC in the state of Arunachal Pradesh (Job No: RW/ITA/STMC/Ar.Pr./23-24/8)
Administrative Approval & Technical Sanction	No. RW/NH/STMC/2023-24/RO-Ita-12900-01, dtd:20.02.2024
Amount put to tender:	Rs. 388.77 Lakhs (Excluding GST)
Time and Date of Opening of Technical Bids:	1530 Hrs of 06.02.2024
List of Firms who participated in the online tender:	1) M/s ATW India Ltd. 2) M/s Lokam Anu Enterprises 3) M/s Mama Enterprise 4) M/s N M Enterprises 5) M/s Puna Hinda 6) M/s Rinya Yangfo Construction 7) M/s Senbom Taipodia 8) M/s Tanor Engineering 9) M/s GRRB Associates 10) M/s D&L Enterprises 11) M/s M.P. Agarwalla 12) M/s Silver Creeks Infra Pvt. Ltd. 13) M/s Vargov Traffic Device System

1. The Administrative & Financial approval and Technical Sanction for the instant work has been accorded by Ministry for an amount of Rs. 4.86 Crore vide letter dated 20.02.2024.

2. The work was bid out in two cover bid system through e-procurement on 30.01.2024 and the technical bids were opened on 06.02.2024.

3. Evaluation Committee examined the documents placed before it. Evaluation sheet is enclosed at Annex-I. Based on the evaluation; committee observed following:

3.1 **M/s ATW India Ltd.:** The Committee observed the following:

- Bidder has not furnished Road Safety Auditor certificate is not attached along with proof of past experience as per Clause 4.3B(b)(ii) of RFP.
 - CA certificate for Turnover not submitted required as per Clause 4.1(f) of RFP.
- Hence, committee found the bidder as **Technically Non-Responsive**.

3.2 **M/s Lokam Anu Enterprises:** The Committee observed the following:

- No similar work of highways as per Clause 4.3(b)(iv) of Section 2 of RFP.
- CVs of key personnel do not have required work experience as per Clause 4.1(e) & 4.3B(b)(ii) of RFP.

Hence, committee found the bidder as **Technically Non-Responsive**.


3.3 **M/s Mama Enterprise:** The Committee observed the following:

- Bidder has not furnished Bid Security in the form of BG required as per Clause 16.2 of RFP.

- Various documents as per Section-3 of RFP not submitted.


Hence, committee found the bidder as **Technically Non-Responsive**.


- 3.4 **M/s NM Enterprises:** The committee found the bidder as **Technically Responsive**.
- 3.5 **M/s Puna Hinda:** The committee found the bidder as **Technically Responsive**.
- 3.6 **M/s Rinya Yangfo Construction:** The Committee observed the following:
a) No similar work of value mentioned in Clause 4.3A b) of RFP.
b) Machinery and key personnel details not as per Cl 1.5 and 1.6 of Section 3 of RFP.
c) No seal of Bank on DD submitted.
Hence, committee found the bidder as **Technically Non-Responsive**.
- 3.7 **M/s Senbom Taipodia:** The Committee observed the following:
a) No similar work of highways as per Clause 4.3(b)(iv) of Section 2 of RFP.
b) CV of key personnel not submitted as per Clause 1.6 of Section 3 of RFP.
Hence, committee found the bidder as **Technically Non-Responsive**.
- 3.8 **M/s Tanor Engineering:** The Committee observed that the Bidder has made misleading statements by hiding value of B. Hence, committee found the bidder as **Technically Non-Responsive** as per **Clause 4.5** of RFP.
- 3.9 **M/s GRRB Associates:** The Committee observed that the CV of Road Safety Auditor is not convincing. Hence, committee found the bidder as **Technically Non-Responsive** as per **Clause 4.3 B(b)(ii)** of RFP.
- 3.10 **M/s D&L Enterprises:** The Committee observed that the experience of Road Safety Auditor undertaking is declared as 3 years which is less than minimum of 5 years required as per Clause 4.3(b)(ii) of Section 2 of RFP. Hence, committee found the bidder as **Technically Non-Responsive** as per **Clause 4.3 B(b)(ii)** of RFP.
- 3.11 **M/s M.P. Agarwalla:** The Committee observed the following:
a) Site Engineer is Diploma not being Graduate required as per minimum requirement as per Clause 4.3(b)(ii) of Section 2 of RFP.
b) Road Safety Auditor are Diploma not being Graduate with no Road Safety auditor certificate required as per Clause 4.3(b)(ii) of Section 2 of RFP.
Hence, committee found the bidder as **Technically Non-Responsive**.
- 3.12 **M/s Silver Creeks Infra Pvt. Ltd.:** The Committee observed the following:
a) No similar nature of work as per Clause 4.3(b)(iv) of Section 2 of RFP.
b) Information of equipment /key personnel not provided in format as specified in Section-3 of RFP.
c) Calculation of Bid capacity not submitted including existing commitment.
Hence, committee found the bidder as **Technically Non-Responsive**.
- 3.13 **M/s Vargov Traffic Device System:** The Committee observed the following:
a) No similar nature of work as per Clause 4.3(b)(iv) of Section 2 of RFP.
b) Road Safety Auditor with no Road Safety auditor certificate proof from approved Govt. Agency required as per **Clause 4.3 B(b)(ii)** of RFP.
Hence, committee found the bidder as **Technically Non-Responsive**.



4. In view of the above, the committee found the following bidders to be technically responsive and subject to confirmation of Bid Security recommended for opening their financial proposals for the work "Repair and Maintenance works on Jonai-Pasighat Road section of NH-515 from Km 510.00 to Km 522.00, Km 522.00 to Km 536.00 & Km 536.00 to Km 550.150 under STMC in the state of Arunachal Pradesh (Job No: RW/ITA/STMC/Ar.Pr./23-24/8)":

- i) M/s NM Enterprises
- ii) M/s Puna Hinda


Junior Engineer
Pasighat Highway Division,
Mariyang


Assistant Engineer
Pasighat Highway Division,
Pangin


Assistant Engineer
Pasighat Highway Division,
Pasighat


Executive Engineer
Pasighat Highway Division, PWD,
Pasighat

*Approved as Recommended by
evaluation Committee.*

01/08/2024.

Chief Engineer
Highways Zone, PWD, AP
Itanagar-791111