

BY ROTATION

Minutes of Meeting of Technical Bid Evaluation held on 03rd December ,2025 under the
Chairmanship of Chief Engineer (Highway Zone), PWD Arunachal Pradesh

Name of Work:	Performance Based Maintenance Contract work on Koronu-Paya Road section of NH-13 from km 650.615 to km 682.396 during the 2025-26 under PBMC in the State of Arunachal Pradesh. [Job No. PBMC/13/Ar.P/2025-26/104]"
Administrative Approval & Technical Sanction	RW/NH/PBMC/2024-25/KP/RO-Ita dated 17.10.2025 Sanctioned cost: -Rs.48.69 Crore
Amount put to tender:	Rs. 36.30 Cr (Excl. GST)
Time and Date of Opening of Technical Bids:	At 12:00 Hrs. on 25.10.2025
List of Firms who participated in the online tender:	1) Bharat Vanijya Eastern Pvt. Ltd 2) Aakshya Infra Projects Pvt Ltd 3) M/s GRRB Associates 4) M/s D&L Enterprises 5) Kaba Infratech Pvt. Ltd 6) Mehlo Enterprises 7) M/s Sher Singh and Company

1. The Administrative & Financial approval and Technical Sanction for the instant work has been accorded by Ministry for an amount of Rs.48.69 Crore vide letter dated 17.10.2025.

2. The work was bid out in two cover bid system through e-procurement on 03.10.2025 and the technical bids were opened on 25.10.2025.

3. The evaluation committee examined the documents placed before the committee. Evaluation sheet is enclosed at Annex-I. Based on the evaluation; the committee observed the following:

3.1. Bharat Vanijya Eastern Pvt. Ltd: The committee observed the following:

a) The Bidder has not furnished documentary evidence in support of equipment as required as per Section-2 : Appendix to ITB of the RFP.

b) Bidder has not furnished Project Manager with 8 yrs experience (as PM/TL) as required as per Clause 4.1.j (2) of Section-2 of RFP..

c) The committee has observed that Road Safety Auditor certificate is without any signature of authority hence cannot be considered valid as per Clause 4.1j(2) of Section of RFP



Hence, the committee found the bidder as **Technically Non-Responsive** as per **Clause 4.1 j(1) and 4.1 j(2) of Section-2 Appendix to ITB of RFP**

3.2. Aakshya Infra Projects Pvt Ltd: The committee observed the following: a) Bidder has not furnished Statement of legal capacity as required as per Clause 4 Qualification of Bidder and Annex-V of Appendix-1A of the RFP.

Hence, the Committee found the bidder as **Technically Non-Responsive** as per **Clause 4(i)(2) of RFP**.

3.3. M/s GRRB Associates: The committee found the bidder as **Technically Responsive**.

3.4. M/s D&L Enterprises: The committee observed the following:

a) The bidder has not furnished documents required to submit physically within the bid due date(time) as per Clause 12.2. Accordingly, the bid is summarily rejected as per Clause 2.20.2 of the RFP. b) Bid has failed the "Test of Responsiveness" as per clause 26 of Submission of Bids of the RFP, so further technical evaluation of Bid is not done.

3.5. Kaba Infratech Pvt. Ltd: The committee observed the following:

a) Bidder has not furnished Project Manager with 8 yrs experience (as PM/TL) as required as per Clause 4.1.j (2) of Section-2 of RFP.

b) The Bidder has not furnished Mobile Maintenance Unit (MMU) documentary evidence in support of equipment as required as per Section-2 of Appendix to ITB of the RFP.

Hence, the committee found the bidder as **Technically Non-Responsive** as per **Clause 4.1 j (2) and Section-2 of Appendix to ITB of the RFP**.

3.6. Mehlo Enterprises: The committee observed the following:

a) The bidder has not executed "one similar work" from Eligible projects in Category 1 and 3 as required as per Clause 4.3(ii) of the RFP.

b) The bidder has not furnished MMU (Mobile Maintenance Unit) documentary evidence in support of equipment as required as per Clause 4.1j (1) of the Section-2 : Appendix to ITB of the RFP.

c) The committee found that the Bidder has not furnished CVs of the technical personnels required as per Clause 4.1 j (2) of Section-2 Appendix to ITB of the RFP.

Hence, the Committee found bidder as **Technically Non-Responsive** as per **Clause 4.3(ii) and Clause 4.1j(1) and (2) of Section 2: Appendix to ITB of the RFP**.


3.7. M/s Sher Singh and Company: The committee observed the following:


a) The bidder has not furnished documents required to submit physically as per Clause 12.2. Accordingly, the bid is summarily rejected as per Clause 2.20.2 of the RFP. b) Bid has failed the "Test of Responsiveness" as per clause 26 of Submission of Bids of the RFP, so further technical evaluation of Bid is not done.

4. In view of the above, the committee found one (01) bidder to be technically responsive and recommended for opening their financial proposals for the Performance

Based Maintenance Contract work on Koronu-Paya Road section of NH-13 from km 650.615 to km 682.396 during the 2025-26 under PBMC in the State of Arunachal Pradesh. [Job No. PBMC/13/Ar.P/2025-26/104].

i. M/s GRRB Associates


Executive Engineer
Jairampur Highway Division,
PWD, Arunachal Pradesh
(Member Secretary)


Representative of Regional Officer, Itanagar
Ministry of Road Transport & Highways
(Member)


Superintending Engineer,
Jairampur Highway Circle,
PWD, Arunachal Pradesh
(Member)


Representative of State Finance Department
Arunachal Pradesh
(Member)


Chief Engineer
Highway Zone, PWD, Arunachal Pradesh
(Chairman)